



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

March 19, 2008

Reviewed: R

Mine Name: Green Peak	Permit Number: M/003/0060
Operator Name: I&P Investments, Inc.	Inspection Date: March 19, 2008
Inspector(s): Lynn Kunzler	Time: 10:30 am
Other Participants: None	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine Inspection while in the area

Inspection Summary:

This site has not been active for the last year. According to BLM permit conditions, the process area along the immigrant trail road was to be reclaimed by now. Currently the operator is trying to work out an agreement with Box Elder County to use this material (waste rock) for county road maintenance, however nothing has yet been finalized.

The area appeared stable with no erosional problems. Trash was being managed. Access road was in good condition.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The operator needs to satisfy the BLM permit conditions. Otherwise, this site is appears to be in compliance at this time. Continue to monitor this site when in the area.

Inspector's Signature [Signature]

LK:pb

cc: Michael Pauletto, Operator
Mike Nelson, BLM- SL FO

O:\M003-BoxElder\M0030060-GreenPeak\inspections\Insp-03192008.doc

080001